



Clean. Reliable. Essential. Every Day.

# Operations & Maintenance Update

David Royall

Assistant General Manager

    [sonomawater.org](https://www.sonomawater.org)



# Tank Maintenance & Recoating

## **Maintenance Complete!**

- Oakmont
- Los Guilicos
- Cotati 1, 2, 3
- Eldridge 1, 2
- Forestville 1, 2
- Kawana Springs 1, 2
- Kastania
- Ralphine 1, 2, 3, 4
- Sonoma 1, 2

## **Recoats Complete**

- Forestville 1, 2
- Kastania
- Cotati 1

## **Recoats Active**

- Cotati 3

## **Recoats on Deck**

- Ralphine 1
- Sonoma 1

## **In Design**

- Ralphine 2
- Sonoma 2



# Eldridge Tank #2 Maintenance



Oxidation encountered in the annular space



Twisted Beams encountered during inspection



# Caisson 5-Pump 10 Replacement

- Pump install, and piping fabrication and installation will be done by late May–early June.
- Caisson back on-line by mid-June.
- Next up:
  - Caisson 5 – Pump 9
  - Caisson 2 – Pump 4



# Occidental Road Well



- Construction is substantially complete on our final Santa Rosa plains well, and ASR pilot study has been conducted.
- All three wells will be run quarterly for the purpose of sampling.
- Our SW Operators will be obtaining samples to ensure readiness should supplemental water sources be needed.



# Emergency Inventory

## **Mortar Lined Steel Pipe**

16" (June 26)

20"

33"

42"

48"

54" (June 26)

## **Next Up:**


Valves, flanges, line stop kits, air valves, elbows, temporary bypass piping



# Tank Security Cameras



New camera at Cotati #1



Camera views from Los Guillicos Tank



*Kawana Tank site is currently having our final cameras installed.*



**Sonoma  
Water**

**Questions?**